



# STAIRCRAFT<sup>®</sup> Group

## Important Stair Specification Improvements

### The Problem

Squeaky stair treads or treads feeling 'spongy' underfoot.



### The Causes

Both problems are the result of stair tread/riser joints becoming loose or detached during the construction process – either by risers being **kicked by safety boots** during the build process or **over zealous use of a bolster** when fitting carpets/gripper rods.



### The Effects

Site remediation prior/post hand-over – at extra cost & time – or customer complaints/call-backs after hand-over.

### The Staircraft Solution

We have a **3x stronger connection** in the tread/riser joint to help reduce your call backs, as we cannot control how our Stairs are stored and installed on site. As you would expect, our connection strength was already comfortably out-performing that demanded by British Standards.



If you have any queries, please get in touch with your designated contact or email



Email Now

Email Now