



# STAIRCRAFT® Group

## Important Stair Specification Improvements

### The Problem

Squeaky stair treads or treads feeling 'spongy' underfoot.



### The Causes

Both problems are the result of stair tread/riser joints becoming loose or detached during the construction process – either by risers being **kicked by safety boots** during the build process or **over zealous use of a bolster** when fitting carpets/gripper rods.



### The Effects

Site remediation prior/post hand-over – at extra cost & time – or customer complaints/call-backs after hand-over.

## The Staircraft Solution

We have a **3x stronger connection in the tread/riser joint** to help reduce your call backs, as we cannot control how our Stairs are stored and installed on site. As you would expect, our connection strength was already comfortably out-performing that demanded by British Standards.

