



STAIRCRAFT®
Group

The Staircraft Difference

The Best Performing Floor-Kits on the Market


1 PROBLEM

Joists too flexible



✓ SOLUTION

Stiffest joist on the market



2 PROBLEM

Separate or missing end blocks



✓ SOLUTION

Factory fixed end blocks




3 PROBLEM

Need to site cut/install perimeter noggings



✓ SOLUTION

Factory notched i-Joists and continuous bracing




4 PROBLEM

Need to cut service holes on site



✓ SOLUTION

Factory cut service holes



5 PROBLEM

Downlights restricted positioning/compromised layout



✓ SOLUTION

Flexibility on downlight positioning. 12.5mm plasterboard for a lighter & easier install




6 PROBLEM

Damaged or unreadable floor plans



✓ SOLUTION

Water/tear proof framing plans with install details on reverse



7 PROBLEM

Lack of install guidance



✓ SOLUTION

i-Joist label provides install guidance via QR code



8 PROBLEM

Vast amounts of decking waste



✓ SOLUTION

Waste-free factory cut decking




9 PROBLEM

Temporary underpropping expensive & restricts working beneath



✓ SOLUTION

Working platform design offers a superior floor with guaranteed savings



10 PROBLEM 1

Improperly protected stairwell openings




PROBLEM 2

Waste from temporary joists, hangers & decking



✓ SOLUTION

WellSafe reusable, rapidly installed fall protection system



For More Information
Contact us Today
sales@staircraftgroup.com

