

Stair Installation Top Tip

The Problem

Stairs are likely to squeak when there is movement between the stair string and the adjacent plasterboard or timber packer.



The Causes

The problem is the result of the stairs not being properly fixed to the adjacent supporting walls.




The Effects

Site remediation prior/post hand-over – at extra cost & time – or customer complaints/call-backs after hand-over.

The Staircraft Solution

Following extensive testing and software development we are the only stair manufacturer able to pre-drill optimised fixing points specifically relating to the flight supplied.



These fixing points highlight where stairs should be fixed and allow simple on-site quality checks during the build process to diminish the risk of squeaking stairs and potential customer care issues post occupancy.

See our other initiative to prevent stair squeaks from occurring

See our other initiative to prevent stair squeaks from occurring




For an easier, quicker and safer installation please refer to our pre-start stair guide.

Download Guide

Download Guide

To Find Everything You Need Download Our App



Or Visit Our Resource Centre

Or Visit Our Resource Centre